

Tidal Barriers Audit Summary Report: Lower Bay of Fundy 2004

By Nicole Hynes

April 2005



Coastal Issues Committee Special Publication Number 5



Ecology Action Centre

ISBN 0-9734181-5-X

Tidal Barriers Audit Summary Report:
Lower Bay of Fundy 2004

By: Nicole Hynes

Edited By: Tony Bowron and Jennifer Graham

Coastal Issues Committee Special Publication Number 5
Ecology Action Centre
April 2005

©2005

All Rights Reserved. Sections of this report may be copied with permission from the authors. Please acknowledge source on all reproduced materials.

The authors wish to thank their funding source:
Fisheries & Oceans Canada – Science & Technology Youth
Internship Program
Bay of Fundy Ecosystem Partnership
Unilever-Evergreen Foundation
Wildlife Habitat Canada
Gulf of Maine Council on the Marine Environment
Nova Scotia Department of Transportation and Public Works

Cover photo by Nicole Hynes.

The photographs displayed within the report taken by Nicole Hynes.

National Library of Canada Cataloguing in Publication Data

Hynes, Nicole. 1980-
Tidal barriers audit summary report: lower Bay of Fundy
2004 / by Nicole Hynes ; edited by Tony Bowron and Jennifer
Graham

(Coastal Issues Committee special publication; no. 5)
Includes bibliographical references.
ISBN 0-9734181-5-X

1. Salt marshes—Nova Scotia—Annapolis (County) 2. Salt
marshes—Nova Scotia—Digby (County) 3. Wetlands restoration—
Nova Scotia—Annapolis (County) 4. Wetlands restoration—Nova
Scotia—Digby (County) 5. Coastal zone management—Nova
Scotia—Annapolis (County) 6. Coastal zone management—Nova
Scotia—Digby (County)

I. Bowron, Tony M. (Tony Mark), 1974- II. Graham, Jennifer, 1971-
III. Ecology Action Centre IV. Title V. Series

QH106.2 N68H95 2005 333.91'880971632
C2005-903705-9

To contact the authors or to obtain additional copies, contact:
Coastal Issues Committee
Ecology Action Centre
1568 Argyle Street Suite 31
Halifax, Nova Scotia
B3J 2B3
Phone: (902) 429-2202 Fax: (902)422-6410
Email: coastal@ecologyaction.ca
Website: www.ecologyaction.ca

Acknowledgements

The author would like to thank those who helped make this report possible:

- The Parker River Clean Water Association, Massachusetts, for developing the original audit methodology and allowing for its modification and use by groups such as ours.
- The members of the Bay of Fundy Ecosystems Partnership (BoFEP) Salt Marsh and Restricted Tidal Systems Working Group, most notably the Conservation Council of New Brunswick, for adapting the Parker River Methodology for use in the Bay of Fundy, and for developing the field data sheets.
- Shayne McQuaid (Stewardship Unit, Habitat Management Division, Fisheries and Oceans Canada) for his continued support and involvement in this project
- Dr. Bob Pett (Nova Scotia Department of Transportation and Public Works) for his support and contributions to the project.
- Roland LeBlanc (Salmon River Salmon Association) for the guided tour of Digby County, the tremendous amount of information provided on the rivers and marshes found in that part of the province and for all his efforts to protect and restore those rivers and wetlands.
- The members of the salt marsh project team – Tony Bowron, Jennifer Graham, Nancy Chiasson, Allison Parker, Phillip Clement and Anne Gregory as well as the many volunteers who helped with the project.

This project was carried out with the financial and in-kind support of:

Fisheries & Oceans Canada – Science & Technology Youth Internship Program
Bay of Fundy Ecosystem Partnership – SMaRTS Working Group
Unilever-Evergreen Foundation
Wildlife Habitat Canada
Gulf of Maine Council on the Marine Environment
Nova Scotia Department of Transportation and Public Works
Saint Mary's University's Community-Based Environmental Monitoring Network

Table of Contents

1.0 Introduction.....	4
2.0 Methodology.....	4
3.0 Results and Discussion	7
3.1 Annapolis County	7
Sites AC1C to AC6C	8
Annapolis River Hydro Dam (DC7A)	9
Moose River (East) (DC8C)	9
3.2 Digby County.....	10
3.2.1 Sites of Interest	10
Winchester Point (DC6C-7C).....	10
Walsh Brook (DC10C)	11
Haight Brook (DC20C).....	12
Post Brook and Henderson Brook (DC21-22A)	12
Cape St. Mary’s Marsh (DC43B-45B)	13
3.2.2 Additional Restricted Sites	14
Chisholm Brook (DC2C)	14
Wade Brook (DC5B)	15
Little Joggins (DC12C and DC13C).....	15
Westport (DC15C).....	16
Freeport (DC16C).....	17
Long Island Brook (DC17C)	17
Little River Wharf (DC19B).....	18
Kinney Brook (DC24B).....	18
Grosses Coques River (DC31B and DC32C).....	19
Duffy Brook system (DC34A).....	20
3.3 Complete List of Tidal Crossings Assessed.....	21
3.4 Study Area Maps Showing Locations of Tidal Crossings Assessed	24
4.0 General Conclusion.....	26
5.0 References and Resources.....	27
Appendix A – Project Background.....	28
Appendix B – Tidal Barriers Audit Data Sheet: Phase I Visual Assessment	29
Appendix C – Tidal Barriers Audit Data Sheet: Phase 2 Tidal Measurements	31

1.0 Introduction

This report summarizes the findings of a tidal barriers audit conducted for the Nov Scotia side of the lower Bay of Fundy as part of the Ecology Action Centre's (EAC) Salt Marsh and Tidal River Restoration Project (Salt Marsh Project). Salt marshes are coastal wetlands found throughout the Bay of Fundy. They are formed from the deposition of sediment into low lying areas and experience daily flooding from the tides, which is essential to their form and function. They provide a range of ecological services which include providing habitat and food for a range of birds, fish and wildlife, protecting against storm surges and erosion, improving water quality, and supporting coastal and marine food webs. Salt marshes also provide recreational, educational and scientific opportunities for surrounding communities.

Unfortunately tidal river and salt marsh systems throughout the Bay of Fundy have been degraded and lost due to the pressures of human activities over the last 400 years. Tidal barriers are structures that prevent the natural movement of tidal waters and species into low lying coastal areas and are a main cause of salt marsh loss in this region. Such barriers can lead to habitat decline, increased erosion, sedimentation, water turbidity, changes in channel size and direction, and the conversion of salt marshes into brackish and freshwater wetlands (Harvey, 2004). They can block fish passage and historical migration routes and result in loss of access to spawning and nursery areas. Barriers can even lead to the total elimination of the marshland. Tidal barriers come in a variety of forms and restrict waterways in a variety of ways. Common man made barriers include dykes, dams, wharves, causeways and road crossings (bridges, culverts and aboiteaux).

For the past five years the EAC's Salt Marsh Project, with the support of project partners and funders, has been identifying tidal barriers and opportunities for salt marsh restoration around the NS side of the Bay of Fundy. An inventory of tidal barriers has been completed for the upper Bay of Fundy (NS side), the results of which are presented in a series of tidal barrier audit reports (see Resources section for a complete list). In 2001 a pilot salt marsh restoration project began at Cheverie Creek, a salt marsh system identified as being tidally restricted by a causeway-culvert during the first tidal barriers audits (for more information on this project see Appendix A or visit www.ecologyaction.ca). This report is a summary of the findings of the tidal barriers audit conducted for the lower Bay of Fundy region, encompassing Annapolis and Digby Counties.

2.0 Methodology

A preliminary visual assessment was conducted on accessible tidal road crossings: bridges, culverts and aboiteaux, along the coast of Digby and Annapolis Counties, to determine which crossings were restricting tidal flow and/or fish passage to salt marsh and tidal rivers. From this it could be established which crossings have the potential to be modified or replaced by less tidally restrictive structures. This methodology was adapted from the Parker River Clean Water Association's *Tidal Crossing Handbook* (Purinton and Mountain, 1998). For more information on the methodologies used in the tidal barriers audits please refer to one of the other EAC tidal barrier reports such as, "*Tidal Barriers and Opportunities for Salt Marsh*

and Tidal River Restoration in the Southern Bight of the Minas Basin, Nova Scotia” (Hynes, Bowron and Duffy 2005).

Potential tidally restrictive sites were first identified using topographical maps and aerial photographs to determine the location, nature of the crossing, type and size of the affected system. This preliminary assessment was followed up by one or more site visits. During the site visits a data sheet was used to help with the assessments and took into account the following factors (for an example of the data sheet used in the visual assessments see Appendix B):

- Visual indicators of restriction (up and downstream): bank slumping, scour pools, water flow, differences in upstream and downstream water levels, ratio of stream width to opening size, divergent channels and vegetation.
- Factors that could potentially influence the assessment: such as weather, tide level and wind.
- Land use: upstream and downstream. Used to determine if land use is contributing to restriction, if there is a possibility of salt marsh recovery (increase in wetland area), and if restoration has the potential to adversely impact adjacent activities.
- Quantitative measurements: tidal crossing and stream dimensions.
- Crossing condition: obvious causes of restriction due to construction or deterioration of crossing, and/or presence of debris.

These factors can contribute to the degree of restriction caused by the crossing and determine if there is a potential for restoration activities. GPS coordinates and photographs were taken at each site for future reference and for inclusion in a Bay of Fundy wide database of tidal barriers being developed by St. Mary’s University.

Each crossing was assigned a degree of restriction, indicating the severity of impact. Categories include:

- *No restriction*: crossings that allow for full tidal flow and cause no ill effects to the upstream system
- *Partial restriction*: crossings that limit tidal flow due to the size, placement, condition of the structure while still allowing for some tidal exchange and retention of wetland function
- *Complete restriction*: crossings that do not allow for any tidal flow through to the upstream
- *No longer tidal*: crossings which no longer experience tidal flow due to activities or structures downstream.

Each tidal crossing that was assessed and determined to be either a partial or complete restriction to tidal flow was assigned a restoration priority level. This indicated which sites have the potential to restore tidal flow and salt marsh habitat to the system. These were based on the observations and data collected through the audit visits. More in depth monitoring could result in a change in these categories. These priority levels were adapted from the Conservation Council of New Brunswick’s 2004 *Return the Tides* campaign publication, “*Tidal Barriers in the Bay of Fundy, New Brunswick Coast.*” (Harvey 2004)

Level 1 (Green) – Small to medium-scale projects that could produce clear environmental benefits and which could be accomplished with modest commitments of time and resources, possibly coordinated by local groups, or handled through routine road maintenance.

Level 2 (Yellow) - High impact barriers requiring high costs, complex engineering solutions, but which would deliver large environmental benefits.

Level 3 (Orange) - Low impact barriers which may not deliver significant environmental benefits.

Level 4 (Red) - Barriers which protect infrastructure or active agricultural land and are not likely eligible for restoration.

Information provided in this report (indicators, degree of restriction, priority levels, etc.) were based on observations made by the tidal barrier auditors at the time of the assessments. Changes may have occurred to certain sites since this date. In addition, since most information detailed in this report was provided through preliminary visual assessments, more in depth examination could result in different ratings.

The study area for this report includes the Bay of Fundy coast for all of Annapolis County and Digby County (Figure 1). This area of coastline contained two main regions, St. Mary's Bay and the Annapolis Basin. Large salt marshes occur along the Annapolis Basin however many of which have been dyked since the settlement of the Acadians in the early 1600's. The North Mountain Range runs long the rest of the Coast of Annapolis County and provides little opportunity for the growth of salt marsh habitat due to rapid rise in elevation. Digby County does not have the large tracts of salt marsh seen elsewhere in the Bay of Fundy. There are a number of moderate sized marshlands and many tidal river systems in the County.




Figure 1. Study Area – Annapolis County and Digby County, Nova Scotia

3.0 Results and Discussion

The comments made in this section are based on the visual assessments made by the tidal barriers auditors during the summer/fall 2004. More in depth monitoring may produce different results. Summaries of the partial and complete restrictions for each county are detailed below. Each site was assigned a code indicating the study area, the sequential number of the site and the type of crossing (A-aboiteau, B-bridge, C-culvert). Information on dykes and aboiteaux across the province is available from the Nova Scotia Department of Agriculture and Fisheries. Only those in close proximity to a road crossing were assessed in this audit.

3.1 Annapolis County

In Annapolis County (AC), only a small number of tidal crossings were assessed, 10 in total, all of which were found in the Annapolis Basin. This was due to the fact that much of the land along the coast of the Annapolis Basin has been dyked for agricultural purposes and the road crossings were either no longer tidal due to this downstream restriction or because many were far enough inland as to not experience tidal influence due to elevation. The North Mountain Range runs along the Bay of Fundy side of Annapolis County and due to the sharp rise in elevation there were few road crossings found to be tidally influenced. Of the 10 tidal crossings that were assessed, 2 had no restrictions, 7 were partial restrictions, and 1 was a complete restriction.

Sites AC1C to AC6C

Partial Restrictions

Location: North side of the Annapolis Basin from Victoria Beach to Annapolis Royal.

Crossing type: There are a series of culverts located along a 15km stretch of Highway 1 along the north side of the Annapolis Basin. With the exception of DC6C most of these culverts are in fair condition and made of either wood or concrete.

Comments: These crossings are summarized together because of their low restoration potential and similar tidal situations. They are not experiencing much tidal influence due to their placement and because of the rise in elevation just upstream of the crossings. With each crossing the potential for an increase in wetland habitat is low. These culverts were all smaller than the width of the streams, and many are placed too high in the creek bed for adequate fish passage. Site DC6C is the only site with significant salt marsh habitat that could potentially benefit from culvert replacement.

The Dentabella and Queen Anne Marshes are found downstream of a number of crossings in this area but were not assessed due to the dyking along the coast of these marshes and the distance that the crossings were inland. Figures 2-7 show the downstream ends of crossings AC1C through AC6C.



Figure 2. AC1C – Thornes Brook, downstream



Figure 3. AC2C – Port Royal, downstream



Figure 4. AC3C – Croscup Brook, downstream.



Figure 5. DC4C – Dixon Brook, downstream



Figure 6. DC5C – Granville, downstream



Figure 7. DC6C – Granville, downstream

Annapolis River Hydro Dam (DC7A)

Complete Restriction

Location: Annapolis Royal

Crossing type: This causeway was constructed in 1960 to protect upstream agricultural dykelands from tidal flooding. In 1984, North America’s first successful tidal power generation station was installed in the causeway, designed with sluice gate and turbine channels (Figure 8).

Comments: Due to the purpose of this structure there is no opportunity for restoring natural tidal flow to the system at this time. There are some dyked marshes around the mouth and edges of the river as well. Installation of the tidal power generation station restored limited tidal flow and fish passage to the system. At such time as the hydro station is decommissioned, replacement of all or part of the causeway with a bridge should be considered.



Figure 8. Causeway and hydropower station at mouth of Annapolis River. Downstream end of one of the dam gates.

Moose River (East) (DC8C)

Partial Restriction

Location: Moose River, Highway 1

Crossing Type: Newly installed concrete culvert, second round culvert sealed off.

Comments: Since this culvert has just recently been installed there is likely little opportunity for replacement. This structure is quite large with an open bottom. Since this river is considerably larger than the culvert opening, a bridge spanning a greater portion of its width might have been the optimal crossing type. There is salt marsh downstream with a house located on the low marsh. Some salt marsh vegetation is present upstream, however, the sharp rise in elevation in a significant limiting factor. A railway crossing, further downstream, does not appear to be restrictive but was not accessible for evaluation.



Figure 9. Downstream end of the new culvert.

3.2 Digby County

In the Digby County (DC) region 48 tidal crossings were assessed along the coast, which included St. Mary's Bay and a portion of the Annapolis Basin. Of these crossings, 21 were determined to be non-restrictive, 19 were partial restrictions, 4 were complete restrictions and 4 were no longer tidal. Overall almost half of the tidal crossings assessed were causing a restriction to tidal flow to some degree.

3.2.1 Sites of Interest

These are sites that have a higher potential for restoration success either because of the greater amount of restorable marsh area, the condition of the crossing, or interest from local groups and residents.

Winchester Point (DC6C-7C)

Complete Restriction

Location: Winchester Point, near mouth of Bear River

Crossing Type: The Winchester Point site consists of 3 culverts within a rail bed approximately 1.8m by 30m long: (DC6C) at the mouth of the system, a culvert through Highway 1 (DC7C) and a drainage culvert through Highway 101 (not assessed here). The rail bed culverts are now buried beneath rock on the south side of the crossing and the wooden support structure has completely collapsed on the north side. Water is seeping

through the rocks where the structure is blocked. The Highway 1 culvert is no longer tidal and is receiving limited water flow due to the downstream blockage.

Comments: The Winchester Point culverts greatly impact the upstream wetland. The 3 culverts and resulting head pond were cleared semi-annually by railroad crews. The water seeping through the rail bed rock foundation is the only tidal water getting through to the upstream because of the complete structural failure of the culverts. This area should be cleared and repaired and most likely replaced by a more appropriately sized and placed structure in order to restore tidal flow, fish passage and increase wetland habitat. Should this occur further assessment would be needed of the Highway 1 culvert (DC7C).



Figure 10. Downstream end of rail bed; culverts completely collapsed (DC6C).



Figure 11. Upstream end of rail bed culverts, completely blocked by rock (DC6C)



Figure 12. Downstream end of Highway 1 culvert (DC7C)

Walsh Brook (DC10C)

Partial Restriction

Location: Big Joggins tributary, Acacia Valley

Crossing Type: This crossing contains a square wooden box culvert, 3.5 meters wide. It is filled with debris and in a considerable state of disrepair. Guardrails along the road are caving in, posing as a safety issue. The structure is also set high above the creek bed.

Comments: This culvert is too small and placed too high in the creek bed to allow for adequate flow of water and species upstream. Large boulders and debris are caving in around the crossing. There are remnants of an old wooden structure along the side of the creek just in front of the downstream end that should be removed to further improve hydrology, although these may not be causing a significant obstruction. This culvert needs to be replaced with a larger more appropriately placed structure. There is potential to improve wetland habitat conditions immediately upstream.



Figure 13. Downstream end of the culvert at low tide, filled with debris and in poor condition

Haight Brook (DC20C)

Partial Restriction

Location: Highway 217, Rossway, Digby Neck.

Crossing Type: This site contains a wooden box culvert, 2.5 meters wide, in poor condition and collecting debris.

Comments: Downstream of the crossing there is a large seawall through which the creek channel has been diverted before being further diverted through this culvert. There are large scour pools at either end of the culvert. Upstream is a large salt marsh system which would greatly benefit from an enlarged opening, which would also improve tidal flow and fish passage to the system. Replacement of the culvert should be considered in combination with the enlargement of the opening in the seawall. Road crossing should be similar in size to the seawall opening and more properly aligned.



Figure 14. Downstream end of culvert

Post Brook and Henderson Brook (DC21-22A)

Complete Restrictions

Location: Marsh Road, head of St. Mary's Bay

Crossing Type: This site contains two aboiteaux (upstream end: concrete/square with two round openings) within a large dyke, completely restricting tidal flow to the upstream system.

Comments: These aboiteaux are located roughly 1.5 km apart and open directly into St. Mary's Bay. Upstream is agricultural land which appears to be currently used primarily for cattle grazing. This site is of significance not only because it once was the largest salt marsh system in St. Mary's Bay, but also because of interest by one of the owners and local community in purchasing the entire dykeland area and restoring it to a functioning salt marsh. If the opportunity arises to do so, these aboiteaux could be removed (or at least the tide gates removed) and the dykes breached (naturally and/or manually), to allow tidal flooding back to the system. This would restore a large amount of converted marsh habitat back to natural conditions but is only possible if the upstream is no longer needed for agricultural purposes.



Figure 15. Upstream end of aboiteaux



Figure 16. Upstream system

Cape St. Mary's Marsh (DC43B-45B)

Partial Restrictions

Location: Mavillette River, Cape St. Mary's

Crossing Type: The wooden bridge (DC45B) located at the mouth of the Cape St. Mary's marsh is 5m wide and opens directly onto the beach. Large boulders and wooden planks extend out around the structure and the channel. Upstream a second wooden bridge (DC44B) crosses the creek and is in need of repair. A concrete bridge that is part of Highway 1 (DC43B) crosses the creek further upstream and is significantly smaller than the channel causing the formation of scour pools and altering the path of water flow.

Comments: The Cape St. Mary's Marsh is a large system that is tidally restricted by the downstream structure at the mouth of the river. The channel has been diverted to flow through this crossing which is too small to supply adequate tidal flooding across the marsh surface and to the river and wetland system extending upstream. This should be replaced with a much larger structure placed inline with the original river path or a second larger opening installed along the roadway in inline with the original channel. The two upstream bridge structures will need to be replaced in the event of increased tidal flow from enlargement of site DC45B. Should this not occur, consideration should still be made to enlarging DC43B as it is too small an opening even under current tidal conditions.

There are two additional crossings further upstream in this system (DC42B, DC41C) but these are at the upper reaches of tidal influence and not causing a large restriction to water flow under current conditions. However, if work is to be done downstream these should be reassessed.



Figure 17. DC45B – Cape St. Mary’s, downstream end.



Figure 18. DC45B – Cape St. Mary’s, upstream end.



Figure 19. DC44B – Cape St. Mary’s, downstream end.



Figure 20. DC43B – Mavillette River, upstream end.

3.2.2 Additional Restricted Sites

These sites range from being slight restrictions (from the pinching of the river channel by a bridge) to sites completely restricting tidal flow to the upstream. For reasons such as land use, small restorable area and crossing status (large bridge, newly installed), they are not high priority for restoration activities at the present time.

Chisholm Brook (DC2C)

Partial Restriction

Location: Tributary of Bear River, Bear River exit road

Crossing Type: Wooden box culvert in poor condition, 3.7m wide.

Comments: This is a small tributary of Bear River that leads to a small salt marsh upstream. There is not a large potential for restoration because of the sharp rise in elevation. Downstream there is fringe salt marsh running along Bear River. While there is not a huge restriction to tidal flow from this crossing when repairs are made it could be enlarged since it is causing erosion, formation of scour pools and there is a difference in stream width.



Figure 21. Downstream of crossing, Bear River system

Wade Brook (DC5B)

Partial Restriction

Location: Bear River

Crossing Type: The site has a 7m concrete bridge with an old dam structure just downstream. The concrete dam spans the width of the creek with a 1-2m opening.

Comments: While the bridge does not represent a restriction to tidal flow the dam opening does and should be removed if no longer serving a purpose. This site is approximately 5km inland and tidal influence may be minimal under normal tidal condition. There is no salt marsh habitat to restore, however, fish passage and water flow would be improved.



Figure 22. Downstream dam

Little Joggins (DC12C and DC13C)

Partial Restriction

Location: Little Joggins, Digby

Crossing Type: Two concrete culverts upstream from an old rail bed spanning the mouth of Little Joggins. Railway crossing could not be assessed due to construction activities at the time of assessment. It was not possible to determine the amount of tidal water moving

through the rail bed or what type of tidal crossing was installed to allow for water movement and fish passage.

Comments: DC12C runs under the cul de sac road and Highway 303 therefore it was not possible to locate the upstream end. It appears the culvert is acting more as a draining area than it is allowing the passage of tidal water upstream. DC13C runs under the cul de sac road which opens into another small marsh before reaching Highway 303 (which also contains a small square concrete drainage culvert). There is a large salt marsh system downstream of these crossings which could be much larger and more productive if it were not for the restriction caused by the rail bed at the mouth of system.

It was not possible to determine the nature of the openings under the rail bed. It was clear from the amount of water built up at the base of the rail bed that the openings are not likely to be adequate in size to allow for natural tidal flow. Assessment of the rail bed is needed to determine the options around opening the system to improve hydrology and wetland habitat. At this time upstream crossings (DC12C and DC13C), as well as the road infrastructure, will need to be reassessed to eliminate the possibility of flooding or damage should modification to the railway be considered.



Figure 23. Downstream view of the marsh system from DC12C.



Figure 24. Rail bed crossing, looking from the upstream crossings.

Westport (DC15C)

Partial Restriction

Location: Westport, Brier Island

Crossing Type: Corrugated culvert 1.5m in diameter, in fair condition. Downstream end of the culvert opens on the beach and is part of a seawall, surrounded by large boulders.

Comments: There is a large scour pool at the upstream end of the culvert and a fair size marsh system. It is bordered by residential houses and an equipment storage area. Enlargement of the culvert would likely improve upstream conditions and reduce erosion (scour pool).



Figure 25. Upstream end of crossing, showing scour pool and upstream system.

Freeport (DC16C)

Partial Restriction

Location: Freeport, Long Island

Crossing Type: Two corrugated culverts, side by side, 0.5m each in diameter, extensive rusting and collecting rock and large woody debris.

Comments: Downstream of the system is a medium sized salt marsh, while the upstream wetland is dominated by freshwater vegetation. These culverts need to be replaced since they are in poor condition. When this occurs a single larger structure should be installed to improve tidal flow upstream and increase tidal marsh habitat upstream.



Figure 26. Downstream end of the culverts, rusted and collecting debris.



Figure 27. Downstream system

Long Island Brook (DC17C)

Partial Restriction

Location: Freeport, Long Island

Crossing Type: Two concrete culverts side by side, 2m each in diameter.

Comments: The downstream end of this crossing opens into the ocean. Upstream the channel is diverted and flows at an angle. This system would be improved by installing a single opening, most likely a bridge since the river is quite large in size. Upstream infrastructure would have to be considered to ensure flooding does not occur.



Figure 28. Upstream system looking from on top of the culverts.

Little River Wharf (DC19B)

Partial Restriction

Location: Little River, Digby Neck

Crossing Type: Concrete bridge structure, 3.8m wide in good condition.

Comments: Since this area is being used as a wharf there may be little potential to restore this area by enlarging the opening. There is a large tidal river and marsh system upstream that could potentially benefit from an increase in natural tidal flooding. The width of the river at the upstream and downstream ends exceeds 20m. Should the opening be enlarged, upstream infrastructure would need to be assessed to determine flood risk.



Figure 29. Downstream end of crossing, much smaller than the width of the river.

Kinney Brook (DC24B)

Partial Restriction

Location: Gilberts Cove, Lighthouse Road off Highway 101

Crossing Type: Wooden bridge 18m in length

Comments: This bridge opens up onto the beach and is pinching the river slightly. Upstream there is a salt marsh system that leads to the Highway 101 bridge (DC25B). The rocks along the base of the structure could be excavated which would allow better tidal flow. This is a large bridge, however, combined with the causeway it does not span the width of the channel and is altering flow.



Figure 30. Upstream end of crossing, bridge is pinching the river channel.

Grosses Coques River (DC31B and DC32C)

Partial Restriction

Location: Grosses Coques, Highway 1

Crossing Type: A concrete bridge (DC31B) crossing at the mouth of this system with an 8.6m opening. A dirt road crosses the river further upstream and is installed with a corrugated culvert (DC32C), 0.7m in diameter.

Comments: The bridge is pinching the river causing a difference in stream widths, scour pools and bank slumping. There is a large wetland up and downstream of this crossing and enlarging the opening should be considered when repairing/replacing this bridge. Upstream a dirt road with a corrugated culvert crosses the river, further restricting tidal flow. This should be enlarged at the same time at the bridge. At the end of this road is a house whose driveway crosses the river and whose yard borders the marsh, however, this appears to be at the edge of the tidal system, with mostly forested land beyond.



Figure 31. Downstream end of DC31B, slightly pinching river channel.



Figure 32. Upstream marsh system



Figure 33. Downstream end of DC32C, undersized for the size of the system.

Duffy Brook system (DC34A)

Complete Restriction

Location: Duffy Brook Aboiteau, Saulnierville

Crossing Type: The downstream end of the aboiteau extends from the dyke and opens onto the beach and is surrounded by large boulders.

Comments: The upstream system is a large freshwater marsh with a number of crossings that are no longer tidal and are not restricting water flow under current conditions. According to local residents fish passage at this site has been addressed and fish can enter the upstream system. Tidal flow could be reintroduced to the system through the removal of the tidal gates on the upstream end of the aboiteau. At that time the size and condition of the upstream crossings would need to be reassessed.



Figure 34. Upstream freshwater marsh system.



Figure 35. Downstream end of aboiteau covered by large boulders.

3.3 Complete List of Tidal Crossings Assessed

Table 1. List of Tidal Crossings Assessed for Annapolis and Digby Counties

Crossing Code	Class	Restriction	Restorable Area	GPS Coordinates	Priority Level
Site AC1C: Thornes Brook	Culvert	Partial	Small	N 44° 41' 59.1'' W 65° 31' 44.16''	3
Site AC2C: Port Royal	Culvert	Partial	Small	N 44° 42' 37.02'' W 65° 38' 6.00''	3
Site AC3C: Croscup Brook	Culvert	Partial	Small	N 44° 42' 41.52'' W 65° 38' 1.26''	3
Site AC4C: Dixon Brook	Culvert	Partial	Small	N 44° 42' 48.54'' W 65° 37' 33.9''	3
Site AC5C: Granville	Culvert	Partial	Small	N 44° 44' 40.5'' W 65° 31' 54.36''	3
Site AC6C: Granville	Culvert	Partial	Small	N 44° 44' 49.02'' W 65° 31' 38.82''	1
Site AC7A: Annapolis River	Dam	Complete	N/A	N 44° 45' 1.56'' W 65° 30' 42.9''	4
Site AC8B: Allains River	Bridge	No restriction	N/A	N 44° 44' 16.74'' W 65° 31' 5.64''	N/A
Site AC9C: Moose River (East)	Culvert	Partial	Small	N 44° 39' 38.58'' W 65° 36' 15.54''	3
Site AC10B: Moose River (West)	Bridge	No restriction	N/A	N 44° 39' 38.58'' W 65° 36' 15.54''	N/A
Site DC1B: Bear River	Bridge	No restriction	N/A	N 44° 36' 57.44'' W 65° 40' 51.87''	N/A
Site DC2C: Chisholm Brook	Culvert	Partial	Small	N 44° 35' 18.78'' W 65° 39' 5.16''	3
Site DC3B: Bear River	Bridge	No restriction	N/A	N 44° 34' 31.68'' W 65° 38' 23.7''	N/A
Site DC4B: Harris Brook	Bridge	No restriction	N/A	N 44° 34' 34.26'' W 65° 38' 19.86''	N/A
Site DC5B: Wade Brook	Bridge	Partial	Small	N 44° 34' 27.42'' W 65° 38' 24.0''	1
Site DC6C: Winchester Pt	Culvert	Complete	Medium	N 44 37' 2.04'' W 65 41' 15.18''	2
Site DC7C: Winchester Pt	Culvert	No longer tidal	N/A	N 44 37' 0.06'' W 65 41' 15.78''	N/A
Site DC8B: Roach Brook	Bridge	No restriction	N/A	N 44° 36' 37.32'' W 65° 42' 53.34''	N/A
Site DC9B: Big Joggins	Bridge	No restriction	N/A	N 44° 36' 2.64'' W 65° 44' 39.96''	N/A
Site DC10C: Walsh Brook	Culvert	Partial	Small	N 44° 35' 43.5'' W 65° 44' 27.47''	1
Site DC11B: Acacia Brook	Bridge	No restriction	N/A	N 44° 34' 59.64'' W 65° 45' 17.4''	N/A
Site DC12C: Little Joggins	Culvert	No restriction	N/A	N 44° 35' 49.98'' W 65° 46' 3.42''	N/A
Site DC13C: Little Joggins	Culvert	Partial	Medium	N 44° 35' 52.2'' W 65° 46' 9.78''	3

Crossing Code	Class	Restriction	Restorable Area	GPS Coordinates	Priority Level
Site DC14B: The Raquette	Bridge	Partial	N/A	N 44° 37' 47.88'' W 65° 45' 57.24''	1
Site DC15C: Westport	Culvert	Partial	Small	N 44° 15' 35.46'' W 66° 21' 6.90''	1
Site DC16C: Freeport	Culvert	Partial	Small	N 44° 16' 35.58'' W 66° 19' 22.5''	1
Site DC17C: Long Island Brook	Culvert	Partial	Medium	N 44° 16' 30.24'' W 66° 19' 5.88''	1
Site DC18B: Long Island Wharf	Bridge	No restriction	N/A	N 44° 23' 34.14'' W 66° 12' 45.96''	N/A
Site DC19B: Little River Wharf	Bridge	Partial	Large	N 44° 26' 41.76'' W 66° 08' 4.96''	1
Site DC20C: Haight Brook	Culvert	Partial	Large	N 44° 34' 46.32'' W 65° 56' 0.72''	1
Site DC21A: Post Brook	Aboiteau	Complete	Large	N 44° 35' 15.54'' W 65° 51' 41.64''	4
Site DC22A: Henderson Brook	Aboiteau	Complete	Large	N 44° 34' 35.7'' W 65° 50' 56.88''	4
Site DC23C: Bingays Brook	Culvert	No restriction	N/A	N 44° 32' 33.12'' W 65° 52' 5.52''	N/A
Site DC24B: Kinney Brook	Bridge	Partial	Small	N 44° 29' 7.44'' W 65° 57' 0.42''	3
Site DC25B: Kinney Brook	Bridge	No restriction	N/A	N 44° 28' 51.66'' W 65° 57' 5.04''	N/A
Site DC26B: Weymouth Harbour	Bridge	No restriction	N/A	N 44° 26' 7.50'' W 66° 00' 6.66''	N/A
Site DC27B: Sissiboo River	Bridge	Partial	Small	N 44° 24' 33.24'' W 65° 59' 46.26''	3
Site DC28B: Sissiboo River	Bridge	No restriction	N/A	N 44° 24' 29.28'' W 65° 57' 24.42''	N/A
Site DC29B: Issacs Lake Brook	Bridge	No restriction	N/A	N 44° 23' 16.02'' W 66° 03' 40.68''	N/A
Site DC30C: Issacs Lake Brook	Culvert	No restriction	N/A	N 44° 23' 13.26'' W 66° 03' 40.62''	N/A
Site DC31B: Grosses Coques River	Bridge	Partial	Small	N 44° 22' 47.52'' W 66° 04' 12.96''	3
Site DC32C: Grosses Coques River	Culvert	Partial	Small	N 44° 22' 26.7'' W 66° 04' 27.72''	1
Site DC33B: Grosses Coque River	Bridge	No restriction	N/A	N 44° 22' 23.34'' W 66° 04' 23.76''	N/A
Site DC34A: Duffy Brook	Aboiteau	Complete	Large	N 44° 15' 6.18'' W 66° 08' 2.1''	1
Site DC35B: Duffy Brook	Bridge	No longer tidal	N/A	N 44° 15' 7.23'' W 66° 07' 50.46''	N/A
Site DC36B: Duffy Brook	Bridge	No longer tidal	N/A	N 44° 15' 4.62'' W 66° 07' 44.22''	N/A
Site DC37B: Duffy Brook	Bridge	No longer tidal	N/A	N 44° 15' 4.02'' W 66° 07' 43.98''	N/A

Crossing Code	Class	Restriction	Restorable Area	GPS Coordinates	Priority Level
Site DC38B: Germain's Brook	Bridge	No restriction	N/A	N 44° 14' 8.16'' W 66° 08' 1.2''	N/A
Site DC39B: Metaghan River	Bridge	No restriction	N/A	N 44° 13' 37.8'' W 66° 07' 11.04''	N/A
Site DC40B: Metaghan River	Bridge	No restriction	N/A	N 44° 13' 8.52'' W 66° 08' 30.6''	N/A
Site DC41C: Mavillette Brook	Culvert	Partial	Small	N 44° 06' 31.14'' W 66° 10' 41.46''	3
Site DC42B: Mavillette Brook	Bridge	Partial	Small	N 44° 06' 15.72'' W 66° 10' 58.38''	3
Site DC43B: Mavillette River	Bridge	Partial	Medium	N 44° 06' 0.36'' W 66° 11' 5.46''	1
Site DC44B: Cape St. Mary's	Bridge	Partial	Small	N 44° 05' 47.16'' W 66° 11' 26.52''	1
Site DC 45B: Cape St. Mary's	Bridge	Partial	Large	N 44° 05' 27.12'' W 66° 11' 40.62''	1
Site DC46B : Bowman Brook	Bridge	No restriction	N/A	N 44° 03' 43.38'' W 66° 10' 12.3''	N/A
Site DC47B: Salmon River	Bridge	No restriction	N/A	N 44° 03' 12.96'' W 66° 09' 41.88''	N/A
Site DC48B: Salmon River	Bridge	No restriction	N/A	N 44° 03' 18.06'' W 66° 09' 10.26''	N/A

Priority Level:

- 1 - Low to medium impact barriers, requiring little cost that can produce obvious ecological benefits
- 2 - High impact barriers requiring high costs, but can produce large ecological benefits
- 3 - Low impact barriers with small ecological benefits
- 4 - Barriers not eligible for restoration due to protection of infrastructure or agricultural land

3.4 Study Area Maps Showing Locations of Tidal Crossings Assessed




Figure 36. Locations of Tidal Crossing Assessed for the Annapolis County and part of Digby County




Figure 37. Locations of Tidal Crossing Assessed for the lower portion of Digby County

4.0 General Conclusion

One of the goals of the EAC's tidal barriers audit work is to increase awareness about the occurrence of tidal barriers throughout the Bay of Fundy and the ecological changes they are causing to our coastal wetlands. It is hoped that individuals, groups and government will be able to use this information to better understand and recognize the implications of coastal development activities and see tidal barriers as a serious problem facing NS's coastal habitats and species. Having an inventory of the tidal crossings around the province will help allow government and communities alike to identify sites within their areas where restoration efforts could be undertaken.

Annapolis County had a small number of tidal crossings assessed in this report because most of the large salt marshes along the Annapolis Basin have been historically dyked. The North Mountain range along the Fundy coast of Annapolis County lessened the potential for the development of large areas of salt marsh and for road crossings to influenced tidal flow and salt marsh habitat.

Digby County has a large number of tidal crossings with a wide range of impacts. The majority of crossings were bridges, however, many of these were still causing some degree of restriction to local hydrology. Almost all of the culverts assessed restricted tidal flow and represented barriers to fish passage and could potentially to be replaced with minimal disruption to adjacent land use and activities. While many of the salt marsh systems in Digby are smaller than those found elsewhere in the Bay of Fundy this audit did identify a number of opportunities to restore tidal wetland habitat and fish passage.

The Bay of Fundy has lost an estimated 80% of its original salt marsh area. Restoration through the removal of tidal barriers is an excellent opportunity to reclaim some of what has been lost. However, it is also important to protect the remaining 20% from being altered, degraded or lost in the first place. Existing salt marshes need to be identified and the public educated on their value.

For more information regarding salt marshes, tidal barriers and restoration, please contact the EAC's Coastal Issues Committee. Other EAC publications on these issues can be found in the following section. The Coastal Issues Committee is also concerned with raising awareness about a variety of other coastal issues facing Nova Scotia's coastlines.

5.0 References and Resources

Bay of Fundy Ecosystem Partnership (BOFEP) website. www.bofep.org

Bowron, T.M. and A. Fitzpatrick. 2001. Assessment of Tidal Restrictions along Hants County's Highway 215: Opportunities and Recommendations for Salt Marsh Restoration. Marine Issues Committee Special Publication Number #9, Ecology Action Centre, Halifax, NS.

Bowron, T.M., J Graham, and M Butler. 1999. Community and Social Considerations in Salt Marsh Restoration Work in Nova Scotia. Ecology Action Centre, Halifax, Nova Scotia.

Cameron, C., T.M. Bowron, J. Hall, M. Butler and J. Graham. 2000. Getting Dirty: the Why and How of Salt Marsh Restoration. Proceedings of the Salt Marsh Restoration Workshop, Wolfville, NS, Nov 5-7, 2000. Marine Issues Committee Special Publication Number 8. Ecology Action Centre, Halifax, Nova Scotia.

Dalton, S and L. Mouland. 2002. Marshes, Tides and Crossings: Colchester County Tidal Barriers Audit Report. Coastal Issues Committee Special Publication Number 1. Ecology Action Centre, Halifax, NS.

Ecology Action Centre website. www.ecologyaction.ca

Harvey, J. 2004. Tidal Barriers in the Bay of Fundy, New Brunswick's Coast. Return the Tides campaign publication. Conservation Council of New Brunswick, Fredericton, NB.

Hynes, N., T.M. Bowron and D. Duffy. 2005. Tidal barriers and Opportunities for Salt Marsh and Tidal River Restoration in Cumberland County, Nova Scotia. Coastal Issues Special Publication Number 3. Ecology Action Centre, Halifax, NS.

Hynes, N., T.M. Bowron and D. Duffy. 2005. Tidal barriers and Opportunities for Salt Marsh and Tidal River Restoration in the Southern Bight of the Minas Basin, Nova Scotia. Coastal Issues Special Publication Number 4. Ecology Action Centre, Halifax, NS.

Koller, Zsofi. 2001. Return the Tides: Tidal Barriers Audit in the Bay of Fundy. Conservation Council of New Brunswick, Fredericton, NB.

Purinton, T.A. and D.C. Mountain, 1998. Tidal Crossing Handbook A Volunteer Guide to Assessing Tidal Restrictions. Parker River Clean Water Association, Byfield, Massachusetts.

Teal, J. and M. Teal. 1969. Life and Death of a Salt Marsh. Little, Brown and Company Ltd. Boston, USA and Toronto, Canada.

Wells, Peter G. 1999. Environmental Impact of Barriers on Rivers Entering the Bay of Fundy: Report of an ad hoc Environment Canada Working Group. Technical Report Series No. 334, Canadian Wildlife Service, Ottawa, ON

Appendix A – Project Background

The **Ecology Action Centre** (EAC) is Nova Scotia's oldest and most active environmental organization. For over three decades the EAC has been a strong advocate for environmental change. Our mission is to encourage a society in Nova Scotia which respects and protects nature and provides environmentally and economically sustainable jobs for its citizens. We have seven active issue committees: Coastal, Energy, Food Action, Marine, Urban, Transportation and Wilderness.

The goal of the **Coastal Issues Committee** (CIC) is to promote coastal conservation and sustainable coastal communities in Nova Scotia. We do this by educating ourselves, the public and government about coastal issues facing Nova Scotia and encourage their involvement and support. We identify habitats at risk and support community efforts to protect them. We review coastal legislation and answer questions from the media and public. Areas we are currently concerned with include habitat loss, coastal access, sustainable coastal industries, coastal development, and coastal policy.

The **Salt Marsh and Tidal Rivers Restoration Project**, of which the tidal barriers audit is a part, has focused on protecting, restoring and raising awareness about the beauty and significance of Nova Scotia's coastal wetlands. Cheverie Creek is our pilot salt marsh restoration site located in Cheverie, NS. This is a tidal river and salt marsh system crossed by a causeway/culvert that partially restricts tidal flow to the upstream habitat. Over the past several years the EAC has been promoting this site for restoration and has conducted field research at the site to collect baseline ecological data about the marsh and to explore the potential for restoration through culvert replacement. Collaboration with project partners, community groups and government agencies resulted in the planning and design of a new crossing aimed at maximizing tidal flow and the restoration of salt marsh habitat and fish passage. Education and community outreach programs are key aspects of the project.



Join the Ecology Action Centre!

Yes! I wish to help the EAC build a healthier, more sustainable Nova Scotia

Name: _____ Phone: _____

Address: _____

Email (for monthly e-newsletter): _____

One Year: \$15 Student/Senior/Unwaged \$30 **Regular** \$50 Contributing/Family \$75 Supporting \$120 Sustaining Other \$ _____

Cash Cheque VISA Mastercard Monthly contribution Auto-renew annually (credit card only)

Name on Card: _____ Card #: _____

Expiry: _____ Signature: _____

Date: _____

Ecology Action Centre, 1568 Argyle St. Halifax, NS, B3J 2B3. Tel. (902) 429-2202 Fax: 422-6410
www.ecologyaction.ca eac@ecologyaction.ca. All memberships and donations are tax deductible.

Appendix B – Tidal Barriers Audit Data Sheet: Phase I Visual Assessment

Visual assessments are to be done approximately two hours before the high tide. Preferably, they will also be done during the peak tides of the lunar cycle.

Name: _____ Date: _____ Time: _____

Location: _____

GPS Coordinates: _____ Crossing code: _____

Weather: [Check Environment Canada web site] _____

Wind velocity and direction: _____

Rain [circle one]: Heavy Moderate Light. Fresh water flow conditions [from station?] _____

Tide conditions [height and time as recorded in tide book, adjusted for area]: High tide _____ Low tide _____ Mean high tide for area [in metres]: _____

Crossing characteristics [circle one]: Bridge; Culvert B corrugated concrete steel PVC wooden block

Crossing condition [circle one]: Is original design intact? Yes No. Describe condition if in need of repair: _____

Width of road [in metres] _____ Length of opening [in metres]: _____

Describe dominant land use or features: Above the crossing: _____

Below the crossing: _____

Restoration potential, if restricted: Area with restoration potential [in hectares] _____

Type of restoration work [circle one]: Culvert repaired Culvert replaced Culvert installed Bridge installed Bridge widened Other _____

Photographic record checklist: Crossing upstream ___ Crossing downstream ___
Landscape upstream ___ Landscape downstream ___ Dominant plants upstream ___
Dominant plants downstream ___ Water flow at crossing: upstream ___ downstream ___
Erosion evidence: upstream ___ downstream ___

Crossing measurements: Please indicate on diagram where measurements were taken

Measurement	Upstream (cm)	Downstream (cm)
Stream width at opening*		
Opening diameter		
Opening height		
Vertical distance, creek bottom to road surface (estimate if necessary, in metres)		

*May be X distance away from opening as long as you are consistent with upstream and downstream.

Bank / channel erosion assessment:

Evidence of bank/channel erosion	Upstream (Yes No)	Downstream (Yes No)
Bank slumping		
Scour pools		
Current channel appears divergent from original channel		
Other		

Flow restriction assessment:

Evidence of flow restriction	Upstream (Yes No)	Downstream (Yes No)
Smooth flow		
Turbulent flow		
Slack (still) water		
Eddies, swirling water		
Flow direction	Upstream	Downstream
Choose one: straight; angular; reversed		
Water level variance	Yes	No
Is there a visible difference in water level on each side of the crossing?		

Vegetation comparison:

Is there a significant difference between downstream and upstream vegetation [circle] : Yes No

Obvious plants	Upstream Yes No	Downstream Yes No
Cordgrass: <i>Spartina alterniflora</i>		
Salt marsh hay: <i>Spartina patens</i>		
Cattails		
Phragmites		
Other?????		

Appendix C – Tidal Barriers Audit Data Sheet: Phase 2 Tidal Measurements

The primary tool for determining whether a crossing is restrictive is the Visual Assessment (Phase 1). Measurements of tidal crossings will be made where it is uncertain whether there is a restriction, or where there is a need for more information about the degree of restriction (Phase 2). Measurements will be made over approximate 6-hour period, from three hours flood tide to three hours ebb tide. Ideally, measurements will be made during the highest tides of the month (spring tide). This should capture a “worst case” normal -- as opposed to abnormal scenario - which would most likely demonstrate restricted flow if there is any. It is important to determine whether the restriction is ongoing or periodic. If possible, the site should be visited twice under different tidal conditions to make this assessment.

Name: _____ GPS Coordinates: _____

Crossing code: _____

Crossing characteristics [circle one]: Bridge Culvert B corrugated concrete steel PVC
wooden block

Visit #1. Date: _____

Weather: [Check Environment Canada web site]: _____

Wind velocity and direction: _____

Rain [circle one]: Heavy Moderate Light. Fresh water flow conditions [from station?]

Tide conditions [height and time as recorded in tide book, adjusted for area]:

High tide _____ Low tide _____

Tidal Range Measurements: [from a reference point on each side of the crossing to the water surface Refer to Tidal Audit Handbook, either Parker River or CCNB version, for a full explanation of the methodology].

Tide Time (high tide = 0)	Actual time	Upstream (in cm)	Actual time	Downstream (in cm)
0 - 3				
0 - 2				
0 - 1.5				
0 - 1				
0 - .5				
0				
0 + .5				
0 + 1				
0 + 1.5				
0 + 2				
0 + 3				